

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	04/25/2018 04/25/2018	Sterling York

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_NA0004_01_s _ 2013_4				
Comment Code					
Inspector Comment					
O&M manuals are located at the district office.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_NA0004_01_s _ 2013_5				
Comment Code					
Inspector Comment					
LMA has adequate emergency flood fight supplies which are at their shop/office located at 214 1st St.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	04/25/2018 04/25/2018	Sterling York

LM Start		Rating **	A	Issue No.	6	
LM End		Issue Type +	Ma	Location *	N/A	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Flood Preparedness & Training				o	
					o	
DWR ID	DWR_NA0004_01_s _ 2013_6					
Comment Code						
Inspector Comment						
NA0004 employees participate in a flood fight training that is sponsored by RD784 each year.						

No Photos

LM Start	0.00	Rating **	M	Issue No.	11
LM End	3.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149571 °	39.164076 °
				-121.601101 °	-121.560876 °
DWR ID	DWR_NA0004_01_s _ 2018_11				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_104\_11\_20180427\_00020.jpg



View looking downstream waterside of the annual vegetation that needs to be maintained, Spring 2018.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	04/25/2018 04/25/2018	Sterling York

LM Start	0.00	Rating **	M	Issue No.	9
LM End	3.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149571 °	39.164075 °
				-121.601101 °	-121.560876 °
DWR ID	DWR_NA0004_01_s_2018_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_104\_9\_20180427\_00021.jpg



View looking downstream landside of the annual vegetation that needs to be maintained, Spring 2018.

LM Start	0.44	Rating **	C	Issue No.	10	
LM End		Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.153083 °		°
				-121.595182 °		°
DWR ID	DWR_NA0004_01_f _ 2017_10					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:223						
Site Designation:LMA-30						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/5/2017						
Notes: Construction work completed. City drainage pipe through levee, exit to river encroaches into patrol road approx. 8 ft so patrol road encroaches into levee 8 ft. From RD, there was a boil near pump house. The site was repaired by RD. The RD has construction documentation and is seeking reimbursement.						

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**


## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	04/25/2018 04/25/2018	Sterling York

LM Start	0.45	Rating **	A/W	Issue No.	37 (cont)
LM End	0.45	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.153107 °	39.153107 °
				-121.594835 °	-121.594835 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:42945					
DS_ID:19090					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through levee, 27 feet below crown. Flap gate and concrete "U" headwall on waterside (WS) end. Slide gate in 48-inch corrugated metal riser on WS slope of pipe. Steel walkway to control gate. Outfall drains from Ellis Lake. Concrete headwall at both toes. Concrete base under riser units. Steel riser unit and slide gate added under Permit No. 4041, 1962-Marysville Levee Commission. [Additional Reference(s): DWR Levee Logs, 1993 and 2005. USACE Sacramento O&M Manual Unit No. 147, August 1955, (Station 8+48)]					
FS Date: 3/14/2013					

Photo 3 of 3 : UCIP\_SP\_2018\_42945\_69742.jpg



View of waterward slope.

LM Start	0.78	Rating **	C	Issue No.	13
LM End	1.39	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			39.156742 °	39.159109 °
				-121.591424 °	-121.589182 °
DWR ID	DWR_NA0004_01_f_2017_13				
Comment Code					
Inspector Comment					
This portion of levee construction was completed October of 2017.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Simmerly Slough	Left	3.23	04/25/2018 04/25/2018	Sterling York

LM Start	1.56	Rating **	A/W	Issue No.	15
LM End	1.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.160854 °	39.160854 °
				-121.587375 °	-121.587375 °
DWR ID	DWR_NA0004_01_f_2016_15				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes where squirrels have been active were backfilled, Spring 2018.					

No Photos

LM Start	1.79	Rating **	C	Issue No.	16	
LM End	1.79	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Animal Control			39.163711 °	39.163711 °	
				-121.584883 °	-121.584883 °	
DWR ID	DWR_NA0004_01_f_2016_16					
Comment Code						
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.						
Inspector Comment						
Rodent holes where squirrels have been active were backfilled, Fall 2017.						

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	04/25/2018 04/25/2018	Sterling York

LM Start	0.01	Rating **	M	Issue No.	3
LM End	1.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149395 °	39.134464 °
				-121.601105 °	-121.594143 °
DWR ID	DWR_NA0004_02_s _ 2018_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_3\_20180427\_00013.jpg



View looking downstream landside of the annual vegetation that needs to be maintained, Spring 2018.

LM Start	0.01	Rating **	M	Issue No.	5
LM End	1.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.149395 °	39.134464 °
				-121.601105 °	-121.594144 °
DWR ID	DWR_NA0004_02_s _ 2018_5				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_5\_20180427\_00012.jpg



View looking downstream waterside of the annual vegetation that needs to be maintained, Spring 2018.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	04/25/2018 04/25/2018	Sterling York

LM Start	0.22	Rating **	M	Issue No.	8
LM End	0.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.146352 °	39.146352 °
				-121.600724 °	-121.600724 °
DWR ID	DWR_NA0004_02_f_2016_8				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Foot path depression in the landside levee slope needs to be repaired. Fall 2016.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_8\_20180302\_00003.jpg



View of foot path depression in the landside levee slope.

LM Start	0.32	Rating **	A/W	Issue No.	4
LM End	0.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.144840 °	39.144840 °
				-121.600559 °	-121.600559 °
DWR ID	DWR_NA0004_02_s_2016_4				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Foot path depression in the landside levee slope has been repaired, Spring 2017.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_4\_20180302\_00001.jpg



View looking downstream of landside slope erosion due to heavy foot traffic. Fall 2016. For Spring 2017 the foot path depression in the landside levee slope has been repaired.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	04/25/2018 04/25/2018	Sterling York

LM Start	0.75	Rating **	M	Issue No.	6
LM End	0.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.138983 °	39.138983 °
				-121.600717 °	-121.600717 °
DWR ID	DWR_NA0004_02_f_2017_6				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes need to be backfilled, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_6\_20180302\_00002.jpg



View of landside of rodent holes, no animal activity was observed, Fall 2017.

LM Start	0.82	Rating **	M	Issue No.	13
LM End	0.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.138827 °	39.138827 °
				-121.599530 °	-121.599530 °
DWR ID	DWR_NA0004_02_f_2016_13				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Foot path depression in the landside levee slope needs to be repaired.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_13\_20180302\_00004.jpg



View of foot path depression in the landside levee slope.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	1.25	04/25/2018 04/25/2018	Sterling York

LM Start	0.85	Rating **	M	Issue No.	14
LM End	0.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.138463 °	39.138463 °
				-121.599168 °	-121.599168 °
DWR ID	DWR_NA0004_02_f_2016_14				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Remove steps that are cut into levee slope, Fall 2017.					

Photo 1 of 1 : SP\_2018\_NA0004\_105\_14\_20180302\_00005.jpg



View of steps for foot path in the landside levee slope, Fall 2017.

LM Start	0.89	Rating **	C	Issue No.	15
LM End	0.89	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.137989 °	39.137989 °
				-121.598756 °	-121.598756 °
DWR ID	DWR_NA0004_02_f_2016_15				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Squirrel holes in the landside levee slope have been back filled, no sign of squirrels. Fall 2017.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	04/25/2018 04/25/2018	Sterling York

LM Start	0.12	Rating **	U	Issue No.	17
LM End	4.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135167 °	39.185036 °
				-121.591631 °	-121.540321 °
DWR ID	DWR_NA0004_03_s_2018_17				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_17\_20180427\_00046.jpg



View looking downstream waterside of the annual vegetation that needs to be maintained, Spring 2018.

LM Start	0.12	Rating **	U	Issue No.	19
LM End	4.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135167 °	39.185036 °
				-121.591631 °	-121.540321 °
DWR ID	DWR_NA0004_03_s_2018_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_19\_20180427\_00047.jpg



View looking upstream waterside of the annual vegetation that needs to be maintained, Spring 2018.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	04/25/2018 04/25/2018	Sterling York

LM Start	1.00	Rating **	M	Issue No.	30
LM End	1.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.142167 °	39.142167 °
				-121.582817 °	-121.582817 °
DWR ID	DWR_NA0004_03_f_2016_30				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Path cut in by foot traffic on the landside slope needs to be repaired.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_30\_20180302\_00009.jpg



View of path cut in by foot traffic on the landside slope.

LM Start	1.16	Rating **	M	Issue No.	32
LM End	1.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.144392 °	39.144392 °
				-121.582930 °	-121.582930 °
DWR ID	DWR_NA0004_03_f_2016_32				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Ruts cut in by vehicle traffic on the landside slope needs to be repaired, Fall 2017.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_32\_20180302\_00010.jpg



View of ruts cut in by vehicle traffic on the waterside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	04/25/2018 04/25/2018	Sterling York

LM Start	1.28	Rating **	M	Issue No.	33
LM End	1.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.145723 °	39.145723 °
				-121.581323 °	-121.581323 °
DWR ID	DWR_NA0004_03_f_2016_33				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Path cut in by foot traffic on the landside slope needs to be repaired, Fall 2017.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_33\_20180302\_00011.jpg



View of path cut in by foot traffic on the landside slope that needs repaired.

LM Start	1.40	Rating **	C	Issue No.	36
LM End	1.40	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.146963 °	39.146963 °
				-121.579830 °	-121.579830 °
DWR ID	DWR_NA0004_03_f_2016_36				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Blackberry bush on levee slope has been removed, Spring 2018.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	04/25/2018 04/25/2018	Sterling York

LM Start	1.61	Rating **	M	Issue No.	18
LM End	1.61	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.149098 °	39.149098 °
				-121.577162 °	-121.577162 °
DWR ID	DWR_NA0004_03_f_2016_18				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Erosion from foot traffic should be repaired, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_18\_20180302\_00006.jpg



View of foot path that has cut into landside levee slope.

LM Start	2.15	Rating **	M	Issue No.	39
LM End	2.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.154440 °	39.154440 °
				-121.569839 °	-121.569839 °
DWR ID	DWR_NA0004_03_f_2016_39				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Erosion from foot traffic should be repaired, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_39\_20180302\_00015.jpg



View looking upstream of foot path that has cut into the landside levee slope.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Marysville Levee Commission

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Yuba River	Right	6.79	04/25/2018 04/25/2018	Sterling York

LM Start	2.21	Rating **	M	Issue No.	40
LM End	2.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.155076 °	39.155076 °
				-121.568970 °	-121.568970 °
DWR ID	DWR_NA0004_03_f_2016_40				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Erosion from foot traffic should be repaired, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_40\_20180302\_00016.jpg



View looking downstream landside of foot path that is cut into the landside levee slope, Fall 2017.

LM Start	2.55	Rating **	M	Issue No.	41
LM End	2.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.158509 °	39.158509 °
				-121.564423 °	-121.564423 °
DWR ID	DWR_NA0004_03_f_2016_41				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Erosion from foot traffic should be repaired, Spring 2018.					

Photo 1 of 1 : SP\_2018\_NA0004\_106\_41\_20180302\_00017.jpg



View looking downstream of foot path that has cut into the landside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---